

CASE STUDY

6,200 GALLON TANK TRANSFORMATION FROM BEAST TO BEAUTY

These 6,200-gallon tank containers were destined for the Caribbean but before they could be loaded with aviation fuel they needed **GEM** to recondition them. Because of the salt water exposure this tank would be exposed to in its new home, it needed the specialized care that **GEM** is well known for in the industry.

The tank was first water jet blasted to remove rust, old paint, and scaling. Next, it was sanded, given a coat of primer and coated with high-quality paint especially used for tank containers. The final step was installing their graphics. A true **GEM**-degree exterior makeover!

BEFORE



AFTER

